

June 29, 2004

Mr. Kenneth N. Weinstein Associate Administrator for Safety Assurance National Highway Traffic Safety Administration 400 Seventh Street, S.W., Room 5321 Washington, D.C. 20590

Dear Mr. Weinstein:

The following information is submitted pursuent to the requirements of 49 CFR part 579.11. General Motors of Japan has decided to conduct a Product Improvement Campaign involving some 2004 Cadillac SRX model vehicles.

This improvement Campaign involves vehicles that were sold outside of the United States. General Motors manufactured these vehicles in the United States and sold substantially similar vehicles in the United States. Please contact me if you have any further questions concerning this report.

Vehicles identified in this letter as "substantially similar" under the broad definition specified in 49 CFR Part 579 and can have significant differences in design, performance, durability, etc. The vehicles may not be "substantially similar" except for purposes of reporting under 49 CFR Part 579.

Sincerely

Gay P. Kent Director

Product Investigations

2004-0003 Attachments



## GENERAL MOTORS CORPORATION 579.11 REPORT

MANUFACTURER: General Motors Corporation

MAKE: Cadillac

MODEL & YEAR: 2004 SRX

NUMBER

OF VEHICLES: 21

**ACTION TYPE** 

**DETERMINATION:** Improvement Campaign / Decision was made by the manufacturer.

CONDITION: Some 2004 SRX model vehicles exported to Jepan could experience a power

ateering hose leak that could result in a lose of power steering assist. Manual

eteering is unaffected.

CORRECTION: Dealers are to replace the power steering loop occlor with a heavy-duty finned

eccier.

DATE OF

DETERMINATION: June 22, 2004.

ACTION

COMMENCED: July 2004.

COUNTRIES

INVOLVED: Japan.

SUBSTANTIALLY

SIMILAR

U.S. VEHICLE: 2004 Cadillac SRX.

<u>COMMENT</u>: This condition has accurred in two of twenty-one vehicles in Japan. The driving

duty cycle in Japan includes more steering wheel input than in the U.S. and steering input increases steering system temperature. The higher frequency of lock-to-lock turns increased steering system temperature on vehicles in Japan with the loop style occler to 180°C and above, where leaks can occur. Consistent with the different duty cycle in the U.S., only two U.S. field incidents are known, making the U.S. rate substantially lower than that in Japan. If power steering assist is lost, the vehicles can be steered manually. Power steering assist is greatest in low speed parking maneuvers that pose minimal risk of a cresh and negligible risk of

injury.